



VIRGINIA FLIGHT SCHOOL SAFETY ARTICLE – NO 02/09

INCIDENT INVESTIGATION AT VFS

INTRODUCTION

An example of a reported occurrence is going to be used to demonstrate the investigative and interventive actions taken by the Safety Section at VFS in mitigation of threats.

SYNOPSIS

After take off and during climb out engine started slight roughness at 800'. On downwind engine ran very rough and lost 400 – 500 RPM

ADDITIONAL INFORMATION

- The aircraft was snagged a few days prior to the incident for the same occurrence – rough running.
- The AMO inspected the aircraft, ran the engine throughout its operating range and found no “roughness”. Aircraft returned to service.

AMO ACTIONS AFTER 2ND SNAGGING:

- Plugs checked for fouling – no fouling.
- Magneto timing checked – correct.
- Induction system checked – no problem.
- AME discusses problem with FSO VFS. Propose checking for sticking valve as suspected by experienced pilot who snagged the aircraft.
- AME isolates cylinder with faulty exhaust valve.
- Cylinder removed. Exhaust valve springs found to have “collapsed” i.e lost their tension.
- Situation caused “valve bounce” which caused excessive valve guide and valve stem wear.

The diagram on the following page illustrates the issue



